




PRODUCT CHANGE NOTIFICATION

RIEDON™ RESISTORS BY BOURNS



Riedon™ Model PF2472 & PF2473 Thick Film Power Resistors by Bourns

Marking Process Change

Riverside, California – July 11, 2024 – In the spirit of continuous improvement, effective March 1, 2022, Riedon implemented several changes to enhance in-house manufacturing capabilities and product performance for the Riedon™ Model PF2472 and PF2473 Thick Film Power Resistors by Bourns*. The marking process resulted in the change from ink printing to laser etching. An internal chip was also updated to improve efficiency. Production for these affected part numbers commenced in the USA and Mexico in March 2022. A list of affected part numbers is included below.

The form changed slightly due to the change to the marking method. The fit and function of the affected part numbers remained the same. The new marking process increased marking durability. The quality and reliability of the affected parts should have been improved as a result of the change. The country of origin changed from Japan to the countries noted above. The first shipments of the affected parts were made in April 2022. Traceability is maintained through lot code and date code (2210).

Samples are available upon request. Bourns recommends that customers test the affected part numbers in their specific applications for verification of satisfactory performance.

If you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

Affected Part Numbers

PF2472-OR015J1	PF2472-OR1F1	PF2472-OR56F1	PF2472-10KF1	PF2472-13RF1	PF2472-1K2F1	PF2472-1R3F1
PF2472-OR01J1	PF2472-OR22F1	PF2472-OR5F1	PF2472-10RF1	PF2472-150RF1	PF2472-1K3F1	PF2472-1R5F1
PF2472-OR02J1	PF2472-OR24F1	PF2472-OR62F1	PF2472-10RF9	PF2472-150RJ1	PF2472-1K5F1	PF2472-1R8F1
PF2472-OR03J1	PF2472-OR27F1	PF2472-OR68F1	PF2472-110RF1	PF2472-150RJ1	PF2472-1K5J1	PF2472-1RF1
PF2472-OR04J1	PF2472-OR2F1	PF2472-OR75F1	PF2472-110RJ1	PF2472-15KF1	PF2472-1K8F1	PF2472-200RF1
PF2472-OR05J1	PF2472-OR33F1	PF2472-OR82F1	PF2472-11KF1	PF2472-15RF1	PF2472-1KF	PF2472-20KF1
PF2472-OR075J1	PF2472-OR36F1	PF2472-OR91F1	PF2472-11RF1	PF2472-15RF2	PF2472-1KF1	PF2472-20RF1
PF2472-OR11F1	PF2472-OR39F1	PF2472-100RF1	PF2472-120RF1	PF2472-180RF1	PF2472-1KF9	PF2472-220RF1
PF2472-OR12F1	PF2472-OR3F1	PF2472-100RF2	PF2472-12KF1	PF2472-18KF1	PF2472-1KJ1	PF2472-22KF1
PF2472-OR13F1	PF2472-OR43F1	PF2472-100RF9	PF2472-12RF1	PF2472-18RF1	PF2472-1KJ1	PF2472-22RF1
PF2472-OR15F1	PF2472-OR47F1	PF2472-100RJ1	PF2472-130RF1	PF2472-1K1F1	PF2472-1R1F1	PF2472-240RF1
PF2472-OR18F1	PF2472-OR51F1	PF2472-100RJ1	PF2472-13KF1	PF2472-1K1J1	PF2472-1R2F1	PF2472-24KF1

~ Continued ~

*Bourns, Inc. acquired substantially all of the assets of Riedon, Inc. in April 2023.

Users should verify that the described changes will not impact the performance of the product in their specific applications.

Affected Part Numbers (Continued)

PF2472-24RF1	PF2472-2RF1	PF2472-3K9F1	PF2472-4R3F1	PF2472-620RF1	PF2472-9K1F1	PF2473-1KF1
PF2472-24RF2	PF2472-300RF1	PF2472-3KF1	PF2472-4R7F1	PF2472-62RF1	PF2472-9R1F1	PF2473-1RF1
PF2472-25KF1	PF2472-300RJ1	PF2472-3KJ1	PF2472-4RF1-A	PF2472-680RF1	PF2473-1K1J1	PF2473-200RF1
PF2472-25RF1	PF2472-300RJ1	PF2472-3KJ1	PF2472-500RF1	PF2472-68RF1	PF2473-20RF1	PF2473-200RJ1
PF2472-270RF1	PF2472-30KF1	PF2472-3R3F1	PF2472-50KF1	PF2472-6K2F1	PF2472-1RF1	PF2473-20RF1
PF2472-27KF1	PF2472-30RF1	PF2472-3R3J1	PF2472-50RF1	PF2472-6K8F1	PF2472-91RF1	PF2473-22RF1
PF2472-27RF1	PF2472-330RF1	PF2472-3R6F1	PF2472-50RJ1	PF2472-6R2F1	PF2472-9R1F1	PF2473-270RF1
PF2472-2K2F1	PF2472-330RJ1	PF2472-3R9F1	PF2472-50RJ1	PF2472-6R8F1	PF2473-0R06F1	PF2473-2KF1
PF2472-2K49F1	PF2472-33KF1	PF2472-3RF1	PF2472-510RF1	PF2472-750RF1	PF2473-0R1F1	PF2473-2R2J1
PF2472-2K4F1	PF2472-33RF1	PF2472-430RF1	PF2472-51RF1	PF2472-75RF1	PF2473-0R5F1	PF2473-2RF1
PF2472-2K7F1	PF2472-360RF1	PF2472-43KF1	PF2472-560RF1	PF2472-7K5F1	PF2473-100RF1	PF2473-32RF1
PF2472-2K7J1	PF2472-36KF1	PF2472-43RF1	PF2472-56RF1	PF2472-7R5F1	PF2473-100RJ1	PF2473-33RF1
PF2472-2KF1	PF2472-36RF1	PF2472-470RF1	PF2472-5K1F1	PF2472-820RF1	PF2473-10RF1	PF2473-470RF1
PF2472-2KJ1	PF2472-390RF1	PF2472-47KF1	PF2472-5K6F1	PF2472-82RF1	PF2473-150RF1	PF2473-470RJ1
PF2472-2KJ1	PF2472-39KF1	PF2472-47RF1	PF2472-5KF1	PF2472-8K2F1	PF2473-150RJ1	PF2473-4RF1
PF2472-2R2F1	PF2472-39RF1	PF2472-4K3F1	PF2472-5R1F1	PF2472-8R2F1	PF2473-1K5F1	PF2473-50RF1
PF2472-2R4F1	PF2472-3K3F1	PF2472-4K7F1	PF2472-5R6F1	PF2472-910RF1	PF2473-1K5J1	PF2473-50RF2
PF2472-2R7F1	PF2472-3K6F1	PF2472-4K7J1	PF2472-5RF1	PF2472-91RF1	PF2473-1K8J1	

"Bourns" is a registered trademark of Bourns, Inc. in the United States and other countries.

In April 2023, BE Services Company, Inc., a subsidiary of Bourns, Inc., purchased certain assets of Riedon, Inc., including its logo and trademarks and the right to continue to manufacture former Riedon™ products.

"Riedon" is a trademark of BE Services Company, Inc.